



**TÜRKİYE  
PETROLLERİ**

**ANONİM ORTAKLIĞI**

**SUMMARY OF TECHNICAL SPECIFICATIONS  
FOR THE 4 WORKOVER RIG SERVICES**

**ENGINEERING DEPARTMENT**

**MAY**

**2026**

## **A. Scope of Work**

This specification covers all workover operations to be carried out via rig in oil, gas, CO<sub>2</sub> production, wastewater and CO<sub>2</sub> injection wells to be determined by TPAO. Although the main working area is the Batman Region, operations may also be conducted at locations in Adiyaman, Thrace, Şırnak and other regions in accordance with TPAO's work schedule. The contractor company shall perform operations such as the completion of existing or newly drilled wells, remedial downhole repairs, well deepening, fishing, well testing, cementing and well control. Even if the contractor company is awarded the tender, it absolutely cannot commence work without fully supplying all the materials it has committed to.

The transportation of the rig and its equipment, their assembly and disassembly on site and the preparation of the site for operations are entirely the responsibility of the contractor. The administrative management, coordination and dispatching of all personnel on site including subcontractors, belong exclusively to the contractor. By strictly applying occupational health and safety rules, the contractor is obligated to provide personal protective equipment to all its personnel, maintain continuous 24-hour cleaning of the worksite and camp/barracks areas and conduct all kinds of rig and equipment maintenance and repair in workshop or parking areas without disruption. Furthermore, the status of fluid stocks present on site throughout the operations, material movements and all daily workover activities must be regularly reported to TPAO; additionally, all necessary support must be provided via rig facilities to other service companies called to the site by TPAO. In order for these services to be executed flawlessly, all consumables and equipment to be used must be supplied in accordance with current industrial API standards and must be in working condition at all times.

It is mandatory for the contractor to supply personal protective equipment (hard hats, fire-retardant coveralls, safety glasses, etc.) for both its own personnel and its subcontractors. Emergency equipment such as gas detectors, outdoor ventilation and breathing sets must always be kept on site against the risks of toxic gases like H<sub>2</sub>S, CO<sub>2</sub> and methane. During operations; site lighting, septic disposal and the evacuation of domestic and chemical waste (engine oil, filters, etc.) in compliance with environmental legislation are the direct responsibility of the contractor.